National Transportation Safety Board FACTUAL REPERT AVIATION

NTSB ID: DCA06MA064 Aircraft Registration Number: N431CA

Occurrence Date: 08/27/2006 Most Critical Injury: Fatal

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Airport Proximity:	Distance Fror	n Landing Facility:		Direction Fro	m Airport:
Lexington	KY		0607	EDT	
Nearest City/Place	State	Zip Code	Local Time	Time Zone	

Aircraft Information Summary

Aircraft Manufacturer	Model/Series	Type of Aircraft
Bombardier, Inc.	CRJ-100	Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On August 27, 2006, about 0607 eastern daylight time, Comair flight 5191, a Bombardier CL-600-2B19 (CRJ-100), N431CA, crashed during takeoff from Blue Grass Airport, Lexington, Kentucky (LEX). The airplane, which had been cleared for runway 22, taxied onto runway 26 instead and ran off the end of runway 26. Of the 47 passengers and 3 crewmembers on board the airplane, 49 were killed, and 1 received serious injuries. The airplane was destroyed by impact forces and postcrash fire. The flight was operating under the provisions of 14 Code of Federal Regulations Part 121 and was en route to Hartsfield-Jackson Atlanta International Airport, Atlanta, Georgia (ATL).

The public docket on this accident is now open and contains factual reports and documentation in the following areas: Operations, Human Performance, Weather, Air Traffic Control, Systems, Structures, Powerplants, Maintenance Records, Survival Factors and Airports, Cockpit Voice Recorder, Flight Data Recorder and Aircraft Performance.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DCA06MA064

Occurrence Date: 08/27/2006

THEIR			00/21/2000										
AVIATION		Occurrence Type: Accident											
Landing Facility/Approach Inf	ormation												
Airport Name			Airport ID:	Airport Eleva	ation	Run	way Used	Runwa	Runway Length		Runw	vay Width	
BLUE GRASS			LEX	979 F	t. MSL	26	26 3500			75			
Runway Surface Type: Asphalt; Concrete													
Runway Surface Condition: Dry													
Type Instrument Approach: NONE													
VFR Approach/Landing: None													
Aircraft Information													
Aircraft Manufacturer Bombardier, Inc.				el/Series J-100					Serial 7472	Number			
Airworthiness Certificate(s): Transport													
Landing Gear Type: Retractable - Tricycle													
Homebuilt Aircraft? No	Number of Seats: 5	54	Certified Max Gross Wt. 53000 LBS						Numbe	er of Eng	ngines: 2		
Engine Type: Turbo Fan	_	Engine Manufacturer: Model/Series: General Electric CF-34-3A1							Rated Power: 8729 LBS				
- Aircraft Inspection Information													
Type of Last Inspection			Date of Last Inspection Time Si			nce Last Insp	Airfram	Airframe Total Time					
Continuous Airworthiness			08/2006	08/2006 0 H					ours 14536 Hours				
- Emergency Locator Transmitter (E	LT) Information												
ELT Installed? No	ELT Operate	ed? No)		ELT	Aided in	n Locating Ac	cident S	Site? No)			
Owner/Operator Information													
Registered Aircraft Owner			Stree	t Address									
First Union National Bank Trust	tee		City Charlotte							State NC	- 1	Zip Code 28202	
			Street	Address						1110		20202	
Operator of Aircraft													
COMAIR INC	City Erlanger							State KY	- 1	Zip Code 41018			
Operator Does Business As:						O	perator Desig	nator Co	ode: CC	MR			
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s):	Flag Carrier/Dom	nestic											
Operating Certificate: Operator Certificate:													
Regulation Flight Conducted Under: Part 121: Air Carrier													
Type of Flight Operation Conducted	: Scheduled; Dor	nestic;	Passeng	er Only									
]	FACT	UAL REP	ORT - AVIAT	ION							Page 2	

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: DCA06MA064

Occurrence Date: 08/27/2006

AVIATI	Occurrence Type: Accident													
First Pilot Information														
Name	City					State	Da	te of Birth	Age					
On File					On File	ile On File					0	n File	35	
Sex: M Seat Occupied:	Left	Prir	ncipal Profes	sion: Occup	ational	nal Pilot Certificate Number: On File								
Certificate(s): Airline Transport; Flight Instructor; Commercial; Sport Pilot														
Airplane Rating(s): Multi-engine Land; Single-engine Land														
Rotorcraft/Glider/LTA: None														
Instrument Rating(s): Airplane														
Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine; Instrument Airplane														
Type Rating/Endorsement for Accident/Incident Aircraft? Current Biennial Flight Review? 07/2006														
Medical Cert.: Class 1	Medica	l Cert. Status	S: With Wai	vers/Limitat	ions	•		Date	of Las	t Medica	ıl Exar	m: 08/2006		
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Night In:		Instrument al Simulated		Rotorc	aft	Glider	Lighter Than Air	
Total Time	4710	3082												
Pilot In Command(PIC)		1567												
Instructor														
Last 90 Days	158	158		158						-				
Last 30 Days	55	55		5				_		+				
Last 24 Hours	3	3		3	<u> </u>		. 5	, 10	.,			157 (0.)(
Seatbelt Used? Yes	Shou	lder Harness	Used? Yes			OXICO	ology Per	formed?	Yes		Seco	nd Pilot? Ye	S .	
Flight Plan/Itinerary														
Type of Flight Plan Filed: IF	R													
Departure Point						State	Д	Airport Identifier			Departure Time		Time Zone	
Same as Accident/Incide	nt Location						L	.EX		ED.				
Destination						State	Δ	Airport Identifier						
Atlanta		GA ATL												
Type of Clearance: IFR														
Type of Airspace:														
Weather Information														
Source of Briefing: Compa	any; Nationa	al Weather S	Service											
Method of Briefing:														
			FACTUAL	REPORT -	- AVIA	TION	N						Page 3	

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: DCA06MA064

Occurrence Date: 08/27/2006

A FTY BOA				Occurren	Accide	nt									
Weather Information															
WOF ID	Observation Time	Time Zone	WC	F Elevat	ion	WOF Distance From Accident Site					Direction From Accident Site				
LEX	0605	EDT		Ft	. MSL				1 NM	eg. Mag.					
Sky/Lowes	st Cloud Condition: Few	1					9000 Ft. AG	iL .	Condition of Light: Night/Dark						
Lowest Ce	iling: None		Ft. AGL			oility:	SM	Alti	meter:	30.00	"Hg				
Temperatu	ıre: 24 °C	Dew Point:		19 °C	Wind	Direction	: 200			Ft.					
Wind Spee	/ind Speed: Gusts: Weather Condtions at Accident Site: Visual Conditions														
Visibility (F	RVR): Ft	. Visibility	y (RVV)		SM	Intensi	ty of Precipita	ation:							
Restriction	s to Visibility: No Obs	curation; No	Precipit	ation											
Type of Pro	ecipitation:														
Accident	Information														
Aircraft Da	mage: Destroyed		А	Aircraft Fire: Ground						Aircraft Explosion None					
Classificati	on:														
- Injury Su	mmary Matrix	Fatal	Serious	Mino	or	None	TOTAL								
First Pi	lot	1					1								
Second	d Pilot			1			1								
Studen	t Pilot							1							
Flight I	nstructor							1							
Check	Pilot							1							
Flight E	Engineer							1							
Cabin A	Attendants	1					1								
Other C	Crew														
Passer	ngers	47					47								
- TOTAL A	ABOARD -	49		1			50	1							
Other 0	Ground														
- GRANE	TOTAL -	49		1			50								

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: DCA06MA064

Occurrence Date: 08/27/2006

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

Joseph M. Sedor

Additional Persons Participating in This Accident/Incident Investigation:

David Keenan Federal Aviation Administration Washington, DC

Scott Granger Air Line Pilot Association Powell Butte, OR

John Coon Blue Grass Airport Lexington, KY

Paul Vislosky Comair Inc. Erlanger, KY

Les McVey GE Transportation Aircraft Engines Cincinnati, OH

David Supplee Intl. Assoc. of Machinists and Aerospace Workers Seminole, FL

Bill Shea National Air Traffic Controllers Association Hurst, TX

Lynn Dziad Teamsters Local 513 Airline Division Florence, KY

Jean-Marc Ledoux Transportaton Safety Board of Canada Dorval, Canada,